

# Photograph Log

**Project Name:**  
**Site Location:**  
**Project Number:**

**McCoy Field**  
**New Bedford, Massachusetts**  
**02685**



**Photo 1:** November 17, 2004 – North detention basin excavation area, photo facing east.



**Photo 2:** November 29, 2004 – South detention basin construction, photo facing north.



**Photo 3:** November 29, 2004 – South detention basin construction, photo facing south.



**Photo 4:** December 3, 2004 – South detention basin construction, facing south.



**Photo 5:** December 6, 2004 – South detention basin construction, facing east.



**Photo 6:** December 6, 2004 – Building footprint pile cap and grade beam excavations, facing southwest.

# Photograph Log

**Project Name:**  
**Site Location:**  
**Project Number:**

**McCoy Field**  
**New Bedford, Massachusetts**  
**02685**



**Photo 7:** December 6, 2004 – Pile cap excavation, closer view, facing northeast.



**Photo 8:** December 6, 2004 – Pile cap excavation, lined prior to backfill, facing northeast.



**Photo 9:** December 6, 2004 – Pile cap excavations, backfilled with crushed stone after lining, photo facing northwest.