

Photograph Log

Project Name:
Site Location:
Date:
Project Number:

McCoy Field
New Bedford, Massachusetts
January 12, 2005
02685



Photo 1: South Detention Basin during gravel backfill (facing South).



Photo 2: South Detention Basin after completion of gravel backfill (facing south-southwest).



Photo 3: North Detention Basin pipe installation and gravel backfilling (facing west-northwest).



Photo 4: North Detention Basin catch basin and manhole (typical).



Photo 5: Typical excavation of pile cap.



Photo 6: Typical geotextile fabric barrier placed in excavated pile cap area.

Photograph Log

Project Name:
Site Location:
Date:
Project Number:

McCoy Field
New Bedford, Massachusetts
January 12, 2005
02685



Photo 7: Partially completed row of pile caps (facing south-southwest).



Photo 8: An example of an area of complete pile cap excavation (facing east).



Photo 9: Example of lined truck used for soil/waste loadout.