



**REPAIRS AT FISH ISLAND BULKHEAD AND FENDER SYSTEM – SITE PHOTOS**



**PROJECT LOCUS**



**PHOTO 1 - DECK W/ STEEL PLATES TO COVER VOID**



PHOTO 2 – SEVERELY CORRODED STEEL BULKHEAD



PHOTO 3 – SEVERELY CORRODED STEEL BULKHEAD



PHOTO 4 – VOID UNDER STEEL PLATE



PHOTO 5 – VOID UNDER STEEL PLATE