

JM Fiske Environmental

NEW BEDFORD REGIONAL AIRPORT
RUNWAY 5-23 – PHASE 4

Reconstruct, Mark, and Groove

Weekly WS Report FINAL

WEEK 25

October 18 to 25, 2014

10/18/2014 (Sat.)

Time: No Inspection

Weather: Sunny 72F

Observer:

10/19/2014 (Sun.)

Time: No Inspection

Weather: Sunny 59

Observer:

10/20/2014 (Mon.)


Time: 7:00 AM – 3:00 P M

Weather: 55 degrees Sunny

Observer: Julia Fiske

Catch Basin #1
outfall west of
Taxiway B water
clear at outfall.





| | | |
|---|--|---|
| <p>Access Road West of New Hanger: Removal of silt fence and haybales.</p> | |  |
| <p>RW23 End: Electrical work continues.</p> | |  |

10/21/2014 (Tue.)


Time: No WS on site. No work in resource areas
Weather: 64 Partly Sunny

Observer –

10/22/2014 (Wed)

Time: No WS on site. No work in resource areas.
Weather: 57 Rainy, 0.87” of Rain

Observer –



JM Fiske Environmental

10/23/2014 (Thu.)

Time: No inspections. No work within resource areas or buffer zones.

Weather: 59 0.63 Rainy

Observer –


10/24/2014 (Fri)

Time: 7:00-3:00.

Weather: 54 overcast

Observer – Julia Fiske

| | | |
|---|--|--|
| <p>Staging Area Hydroseeding of the staging area</p> | |  |
| <p>RW 23 End: Hydroseeding of MALSR</p> | |  |



| | | |
|---|--|---|
| <p>Wetland Replication Area Erosion Control Blanket being installed in upland buffer</p> | |  |
| <p>Wetland Replication Area: Woody debris installed within replication area.</p> | |  |